

工事写真帳
(着工前・完成)

工事名 令和2年度 旧中央衛生センター解体工事

工事場所 青森県弘前市大字高杉字神原282番地136

工期 着手：令和2年7月22日

竣工：令和4年3月25日

発注者 弘前地区環境整備事務組合

施工者 アサヒ・丸勘・村上特定建設工事共同企業体

Blank lined area for photographs.

着工前

処理棟

2020.7.29



完成写真

2021.11.13

着工前

処理棟

2020.7.29



完成写真

2021.11.13

着工前

処理棟

2020.7.29



完成写真

2021.11.13

着工前

処理棟

2020.7.29



着工前

処理棟

2020.7.29



着工前

処理棟

2020.7.29



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

管理棟

2020.7.29



着工前

管理棟

2020.7.29



着工前

管理棟

2020.7.29



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

管理棟

2020.7.29



着工前

管理棟

2020.7.29



着工前

管理棟

2020.7.29



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13



着工前

連絡通路

2020.7.29



着工前

連絡通路

2020.7.29



完成写真

2021.11.13



完成写真

2021.11.13



着工前

車庫

2020.7.29



完成写真

2021.11.13

着工前

車庫

2020.7.29



完成写真

2021.11.13

着工前

車庫

2020.7.29



完成写真

2021.11.13

着工前

ポンプ室

2020.7.29



着工前

ポンプ室

2020.7.29



完成写真

2021.11.13



完成写真

2021.11.13

着工前

クーリングタワー



2020.7.29

着工前

クーリングタワー



2020.7.29



完成写真

2021.11.13



完成写真

2021.11.13

着工前

フェンス

2020.8.5



完成写真

2021.11.13

着工前

フェンス

2020.8.5



完成写真

2021.11.13

着工前

フェンス

2020.8.5



完成写真

2021.11.13

着工前

フェンス

2020.8.5



完成写真

2021.11.13

着工前

フェンス

2020.8.5



完成写真

2021.11.13

着工前

フェンス

2020.8.5



完成写真

2021.11.13

着工前

門・扉

2020.8.5



着工前

門・扉

2020.8.5



着工前

門・扉

2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

門・扉

2020.8.5



着工前

門・扉

2020.8.5



着工前

門・扉

2020.8.5




完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13



着工前

樹木・緑地

2020.8.5



完成写真

2021.11.13

着工前

樹木・緑地

2020.8.5



完成写真

2021.11.13

着工前

樹木・緑地

2020.8.5



完成写真

2021.11.13

着工前

樹木・緑地

2020.8.5



着工前

樹木・緑地

2020.8.5



着工前

樹木・緑地

2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

樹木・緑地

2020.8.5



着工前

樹木・緑地

2020.8.5



着工前

樹木・緑地

2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



着工前

アスファルト・縁石

融雪埋設管

2020.8.5



着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前
 アスファルト・縁石
 融雪埋設管



2020.8.5



完成写真

2021.11.13

着工前
 アスファルト・縁石
 融雪埋設管



2020.8.5



完成写真

2021.11.13

着工前
 アスファルト・縁石
 融雪埋設管



2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管



2020.8.5

着工前

アスファルト・縁石

融雪埋設管



2020.8.5

着工前

アスファルト・縁石

融雪埋設管



2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



着工前

アスファルト・縁石

融雪埋設管

2020.8.5



着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13



完成写真

2021.11.13

着工前

アスファルト・縁石

融雪埋設管

2020.8.5



着工前

アスファルト・縁石

融雪埋設管

2020.8.5



完成写真

2021.11.13



完成写真

2021.11.13